



Shop Name: Automobilių patikra prieš pirkimą
Tel: +37067917255
Email: info@sauliusproauto.lt
Address: --

Report ID: MAXIA20261014133732
Test Time: 2026-10-14 13:37:32
Technician: saulius

-08/2020 Toyota Pre-scan Report

Vehicle Information

08/2020/Toyota/Rav4 HV/A25A-FXS
VIN: [REDACTED]

Odometer Reading: 176048km
License Plate: --



Scan to download
PDF

Customer Information

Name: --

Tel: --

Device information

Scanner: MaxiSys MS906MAX
Version: V7.60

Serial Number: V6DGS9V01123
Repair Order Number: [REDACTED]



System Scanned (40)

System	Calibration	Status/DTC
Engine		✓ 0
Hybrid control		✓ 0
Electric parking brake		✓ 0
ABS/VSC/TRC		✓ 0
SRS airbag		✓ 0
Combination meter		✓ 0
Tire pressure monitor	ADAS	✓ 0
Main body		✓ 0
Master switch		✓ 0
Driver door motor		✓ 0
Driver seat		✓ 0
Right rear door motor		✓ 0
Left rear door motor		✓ 0
Passenger door motor		✓ 0
Back door		✓ 0
Rain and/or humidity sensor		✓ 0
Pre-Collision system	ADAS	✓ 0
Air conditioner		✓ 0
Motor generator		✓ 0
Rear motor generator		✓ 0



Telematics		✓ 0
Blind spot monitor (BSM) slave	ADAS	✓ 0
Blind spot monitor (BSM) master	ADAS	✓ 0
Front radar sensor	ADAS	✓ 0
Navigation system		✓ 0
Power source control		✓ 0
Entry&Start		✓ 0
Front recognition camera (Front lighting control)	ADAS	✓ 0
Headlamp auto leveling (Sub)	ADAS	✓ 0
Headlamp auto leveling	ADAS	✓ 0
Clearance warning	ADAS	✓ 0
Road sign assist	ADAS	✓ 0
Radar cruise 1	ADAS	✓ 0
Radar cruise 2	ADAS	✓ 0
EMPS		✓ 0
Front recognition camera	ADAS	✓ 0
Lane control	ADAS	✓ 0
Circumference monitoring camera control module	ADAS	✓ 0
Steering angle sensor (SAS)		✓ 0
Central gateway		✓ 0

 Pre-scan DTC (0)**Pre-scan Technician Notes**

Customer name: _____

Technician: _____

Date: _____



Note: Please save a copy of this report for your records.